

[Suggestion for reducing man-hours] Screen number auto-remapping feature saves your labor time!

Before

I needed to adjust the screen numbers to display assigned to each navigation button after I moved some screens.

It takes so much works to change all the settings manually...




Screen numbers assigned to these navigation buttons must be changed to the new numbers.

Try auto-remapping function!

After


After moving the screens in the Screen List, the target screen numbers are automatically remapped to the new ones!

It is fail-proof and helps to reduce time and effort!




Easy setting!

Simply check the option box below from [File] > [Property] > [Edit] window!



Then, go to [Home] > [Screen List] and move the screens!



- * Auto-remapping is not applied in any of the following cases:
 - Using [Cut] and [Paste] in the Screen List
 - Using SYS(SET_SCRN) or SYS(SET_MOVLP) macro command

Registration items and parts which have auto-remapping function

- Screen




Function: Screen Change-over
 Word Operation
 Write

} The screen numbers to move specified in the switches with any of these functions

- Screen Library



The call number of the screen library placed on a screen




- Overlap Library



Call Overlap



Function: Overlap Control



Num. Display



Char. Display

Function: Entry target and Display the keyboard

} The overlap library number specified in any of these items